



# **Coating Thickness Gauge**



Operating manual



# **Language Contents**

Language	page
English	2-3
Svenska	4-5
Norsk	6-7
Dansk	8-9
Suomi	10-11
Deutsch	12-13
Nederlands	14-15
Français	16-17
Italiano	18-19
Español	20-21
Português	
Ελληνίκά	
Polski	26-27
Eesti	28_29
LietuviŠkai	30-31
Latviski	32-33
Русский	34-35



## Coating Thickness Gauge Limit 5100.

#### General information

Limit 5100 measure thickness of coating. E.g. paint, plastic, porcelain enamel, copper, zinc, aluminium, chrome galvanizing layer on magnetic and non-magnetic materials.

## Specification

Range  $0-1000 \, \mu m$ 

Reading 0-100  $\mu$ m 0,1  $\mu$ m

100-1000 μm 1 μm

Accuracy  $\pm$  2,5  $\mu$ m or 1-3 %. Battery  $\pm$  4 st 1,5 V AAA Automatic off After 2 minuts

### Operation

1. On or manuell OFF. Push the Θ-button.

The instrument will be auto-calibrate so always keep the probe away from any metal for 3 seconds after power on.

- 2. Select magnetic or non-magnetic material with N/NF button. The display indicate Fe for magnetic material or NFe for non-magnetic material.
- 3. Select µm for reading in 1/1000 mm.
- 4. Place the probe on an layer to be measured. Read the coating thickness on the display.
- 5. For next measurement lift the probe more than 10 mm and repeat the measurement.



### Calibration

- 1. Place the probe on an uncoated area.
- 2. Push the ZERO button.
- 3. Lift the probe.
- Select a calibration foil according to your measurement range. Measure the calibration foil on the uncoated area.
- Lift the probe and adjust with the ▲ ▼ buttons the value on the display to same value as foil.
- Repeat the test measurement and adjust the value until the result is correct.

It is recommended that calibration is made on same material as to be measured.

## Replace battery

When battery symbol shows on the display. Remove the battery lid on backside and replace with 4 pcs 1,5 V batterys type AAA.